



Every mark on this sheet uses only the cyan channel.



Tint ladder, 100% to 5%



Fine lines



A gap in the block or a missing line is a clogged nozzle on this channel; a wrong shade means a mixed or refilled cartridge.